



70000 Degreaser Extra P-60

Document version: November 29th 2017



Description

Especially suitable for the removal of heavy industrial soiling such as grease, lubricants, tar, asphalt and bitumen. Easily cleans machine parts and sheet metal. Formulated with powerful emulsifiers for optimal dilution with water. Absorbs about 5 times the volume of contamination (oil and grease). Flash point is approximately 65°C. Includes aromatics.

Dosage and Use

For manual cleaning use the product preferably undiluted. Let the product penetrate for some while. Then allow to evaporate, wipe with a cloth or brush, or spray with water. For high pressure cleaning and spray washing preferably dilute 1%-2% (1:100-1:50) and process at approximately 60°C.

Packing units

ART. NO.	VOLUME	ITEMS PER UNIT	ITEMS PER PALLET
70001	1 L	12	450
70005	5 L	4	112
70020	20 L	1	30
70060	60 L	1	12
70205	205 L	1	2
70205B	205 L	1	2
P70000	bulk	1	-